CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date E141522 E141522-20210930 2022-JANUARY-12

Issued to: TURCK INC. 3000 CAMPUS DRIVE MINNEAPOLIS, MN 55441-2619 UNITED STATES

This certificate confirms that representative samples of

ms that CABLE ASSEMBLIES AND FITTINGS FOR INDUSTRIAL ples of CONTROL AND SIGNAL See Addendum Page for Models

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:UL 2238 - The Standard for Safety for Cable Assemblies
and Fittings for Industrial Control and Signal Distribution
CSA C22.2 No. 182.3-16 - Special Use Attachment Plugs,
Receptacles and ConnectorsAdditional Information:See the UL Online Certifications Directory at
https://ig.ulprospector.com for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Ba Mall

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, plea contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

CERTIFICATE OF COMPLIANCE

Certificate Number Report Reference Issue Date E141522 E141522-20210930 2022-JANUARY-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Cable connectors; FW-M8ST4-G-SB-ME-SH-6.5, FW-PRKPM0320-SA-S-0406, FW-PRKPM0420-SA-S-0406, FW-PRSPM0320-SA-S-0406, FW-PRSPM0420-SA-S-0406, FW-ERKPM0416-SA-S-0408, FW-ERKPM0516-SA-S-0408, FW-ERSPM0416-SA-S-0408, FW-EWSPM0516-SA-S-0408, FW-EWSPM0416-SA-S-0408, FW-EWSPM0516-SA-S-0408, FW-EWSPM0

Cable connectors USL Only; CMBD8181-0

Barnelly

Bruce Mahrenholz, Director North American Certification Program



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/